5.pdf 23/11/09 4:32:54 PM

Proto-chair



Level 5 1:50



Level 4 1:50



10m of stainless steel - bent with no cuts or joins

Angles between elements are three dimensionally equal so that the square timber meets evenly. Angles do not need to be the same at every joint.



Even angles meet cleanly

Uneven angles are complex



Developable surface maximises ratio of opening area to surface area